



**Chevron Chemical Company**

595 Market Street, San Francisco, California  
Mail Address: P.O. Box 3883, San Francisco, CA 94119

SITE: Cherrom-Ortho  
BREAK: 11.9 v2  
OTHER: \_\_\_\_\_

April 29, 1982

Orlando, Florida  
Subsurface Investigation

Mr. R. A. Uttal  
Central Florida Mack Trucks  
3100 N. Orange Blossom Trail  
Orlando, FL 32804

Dear Mr. Uttal:

As we discussed, Chevron Chemical Company has completed the first set of groundwater analysis at your location. The results from those analyses show only very low levels of contaminants. In order to assure this conclusion is correct, Chevron has asked Dames and Moore to install three additional wells and conduct another set of chemical analysis. Dames and Moore will provide a final report to Chevron after completion of this phase covering both set of samples.

Chevron will provide you with a summary of the final results from these studies. If you have any questions about the status of these investigations, please feel free to contact me at (415) 894-9076.

Sincerely,

K. C. Bishop III  
Senior Environmental Engineer

KCB:aw



10482931